



Asia Pacific Processing Center

SAN SCREEN CONFIGURATION CHANGES AND LOG REVIEW

Log Reviewed By

Name : **ASHOK KUMAR REDDY**

Date : 01/12/2006

Signature : 

Approved By

Name : **KRISHNAKUMAR PAZORE**

Date : 1-12-2006

Signature :



12/1/06 11:29 AM	+ Link removed between Host SSUNU63b port 10:00...:5F and Switch CNX11SW1 port fc9 (by datasource CNX09CT)
	+ Link removed between Generic Device 20:00:00:00:C9:47:15:C5 port 10:00...:C5 and Switch CNX09SW1 port fc9 (by datasource CNX09CT)
	+ Host SSUNU63b is down (by datasource CNX09CT)
	+ Generic Device 20:00:00:00:C9:47:15:C5 is down (by datasource CNX09CT)
	+ Switch CNX09SW1 configuration changed (by datasource CNX09CT) ✓
	+ Switch CNX11SW1 configuration changed (by datasource CNX09CT)
12/1/06 11:13 AM	+ 3 Violations resolved between Host APACSGWINU1151 and Storage USP@163.37.197.72 (by datasource CNX07)
	+ Link added between Host APACSGWINU1151 port 10:00...:D4 and Switch CNX07_SW2_ED140M2 port fc110 (by datasource CNX07) ✓
	+ Host APACSGWINU1151 is up (by datasource CNX07)
	+ Switch CNX07_SW2_ED140M2 configuration changed (by datasource CNX07)
12/1/06 11:11 AM	+ 3 Violations created between Host APACSGWINU1151 and Storage USP@163.37.197.72 (by datasource CNX07)
	+ Link removed between Host APACSGWINU1151 port 10:00...:D4 and Switch CNX07_SW2_ED140M2 port fc110 (by datasource CNX07) ✓
	+ Host APACSGWINU1151 is down (by datasource CNX07)
	+ Switch CNX07_SW2_ED140M2 configuration changed (by datasource CNX07)
12/1/06 9:46 AM	Number of ports in Host GCBAPP167 that can access Storage USP@163.37.197.72 changed from 1 to 2 for Volume list: 01:74, 01:EA, 01:F4 (by datasource CNX05)
	+ Link added between Host GCBAPP167 port 10:00...:83 and Switch CT_CNX05_ED140_SW1 port fc114 (by datasource CNX05)
	+ Switch CT_CNX05_ED140_SW1 configuration changed (by datasource CNX05) ✓
	+ Host GCBAPP167 configuration changed (by datasource CNX05)
12/1/06 9:33 AM	+ 3 Violations resolved between Host GCBAPP167 and Storage USP@163.37.197.72 (by datasource CNX07)
	+ Link added between Host GCBAPP167 port 10:00...:67 and Switch CNX07_SW2_ED140M2 port fc114 (by datasource CNX07)
	+ Host GCBAPP167 is up (by datasource CNX07) ✓
	+ Switch CNX07_SW2_ED140M2 configuration changed (by datasource CNX07)
12/1/06 9:31 AM	+ 3 Violations created between Host GCBAPP167 and Storage USP@163.37.197.72 (by datasource CNX07)
	+ Link removed between Host GCBAPP167 port 10:00...:67 and Switch CNX07_SW2_ED140M2 port fc114 (by datasource CNX07) ✓
	+ Host GCBAPP167 is down (by datasource CNX07)
	+ Switch CNX07_SW2_ED140M2 configuration changed (by datasource CNX07)
12/1/06 9:31 AM	Number of ports in Host GCBAPP167 that can access Storage USP@163.37.197.72 changed from 2 to 1 for Volume list: 01:74, 01:EA, 01:F4 (by datasource CNX05)
	+ Link removed between Host GCBAPP167 port 10:00...:83 and Switch CT_CNX05_ED140_SW1 port fc114 (by datasource CNX05)
	+ Switch CT_CNX05_ED140_SW1 configuration changed (by datasource CNX05) ✓
	+ Host GCBAPP167 configuration changed (by datasource CNX05)
12/1/06 5:11 AM	+ Link added between Host SHPP40 port 50:06...:E2 and Switch CT_CNX07_ED140M_SW1 port fc26 (by datasource CNX07)
	+ Switch CT_CNX07_ED140M_SW1 configuration changed (by datasource CNX07) ✓
	+ Host SHPP40 configuration changed (by datasource CNX07)
12/1/06 5:07 AM	+ Link removed between Host SHPP40 port 50:06...:E2 and Switch CT_CNX07_ED140M_SW1 port fc26 (by datasource CNX07)
	+ Switch CT_CNX07_ED140M_SW1 configuration changed (by datasource CNX07) ✓
	+ Host SHPP40 configuration changed (by datasource CNX07)
11/30/06 7:13 PM	+ 5 Violations resolved between Host SHPU57 and Storage Sym-00937 (by datasource CNX09CT)

	+ 5 Violations resolved between Host SHPU58 and Storage Sym-00937 (by datasource CNX09CT)
	+ Link added between Host SHPU57 port 50:06...A4 and Switch CT_CN11_SW3 port fc37 (by datasource CNX09CT)
	+ Link added between Host SHPU57 port 50:06...9C and Switch CT_CN11_SW2 port fc37 (by datasource CNX09CT)
	+ Link added between Host SHPU58 port 50:06...34 and Switch CT_CN11_SW3 port fc38 (by datasource CNX09CT)
	+ Link added between Host SHPU58 port 50:06...54 and Switch CT_CN11_SW2 port fc38 (by datasource CNX09CT)
	+ Host SHPU57 is up (by datasource CNX09CT)
	+ Host SHPU58 is up (by datasource CNX09CT)
	+ Switch CT_CN11_SW2 configuration changed (by datasource CNX09CT)
	+ Switch CT_CN11_SW3 configuration changed (by datasource CNX09CT)
11/30/06 7:08 PM	+ Link added between Host SSUNDBP07 port 10:00...28 and Switch CNX34SW1 port fc10 (by datasource CNX32_34)
	+ Link added between Host SSUNDBP07 port 10:00...43 and Switch CNX32SW3 port fc22 (by datasource CNX32_34)
	+ Link added between Host SSUNDBP07 port 10:00...44 and Switch CNX32SW1 port fc10 (by datasource CNX32_34)
	+ Switch CNX32SW1 configuration changed (by datasource CNX32_34)
	+ Switch CNX32SW3 configuration changed (by datasource CNX32_34)
	+ Switch CNX34SW1 configuration changed (by datasource CNX32_34)
	+ Host SSUNDBP07 configuration changed (by datasource CNX32_34)
11/30/06 7:06 PM	+ Link removed between Host SSUNDBP07 port 10:00...28 and Switch CNX34SW1 port fc10 (by datasource CNX32_34)
	+ Link removed between Host SSUNDBP07 port 10:00...43 and Switch CNX32SW3 port fc22 (by datasource CNX32_34)
	+ Link removed between Host SSUNDBP07 port 10:00...44 and Switch CNX32SW1 port fc10 (by datasource CNX32_34)
	+ Switch CNX32SW1 configuration changed (by datasource CNX32_34)
	+ Switch CNX32SW3 configuration changed (by datasource CNX32_34)
	+ Switch CNX34SW1 configuration changed (by datasource CNX32_34)
	+ Host SSUNDBP07 configuration changed (by datasource CNX32_34)
11/30/06 6:58 PM	+ Link added between Host SSUNDBP06 port 10:00...5E and Switch CNX34SW1 port fc7 (by datasource CNX32_34)
	+ Link added between Host SSUNDBP06 port 10:00...49 and Switch CNX32SW3 port fc17 (by datasource CNX32_34)
	+ Link added between Host SSUNDBP06 port 10:00...4A and Switch CNX32SW1 port fc7 (by datasource CNX32_34)
	+ Switch CNX32SW1 configuration changed (by datasource CNX32_34)
	+ Switch CNX32SW3 configuration changed (by datasource CNX32_34)
	+ Switch CNX34SW1 configuration changed (by datasource CNX32_34)
	+ Host SSUNDBP06 configuration changed (by datasource CNX32_34)
11/30/06 6:58 PM	+ Link added between Generic Device 50:06:0B:00:00:2A:3E:C9 port 50:06...C8 and Switch CNX11SW2 port fc37 (by datasource CNX09CT)
	+ Link added between Generic Device 50:06:0B:00:00:2A:3F:A1 port 50:06...A0 and Switch CNX11SW2 port fc38 (by datasource CNX09CT)
	Generic Device 50:06:0B:00:00:2A:3E:C9 is up (by datasource CNX09CT)
	Generic Device 50:06:0B:00:00:2A:3F:A1 is up (by datasource CNX09CT)
	+ Switch CNX11SW2 configuration changed (by datasource CNX09CT)
11/30/06 6:56 PM	+ Link removed between Host SSUNDBP06 port 10:00...5E and Switch CNX34SW1 port fc7 (by datasource CNX32_34)
	+ Link removed between Host SSUNDBP06 port 10:00...49 and Switch CNX32SW3 port fc17 (by datasource CNX32_34)
	+ Link removed between Host SSUNDBP06 port 10:00...4A and Switch CNX32SW1 port fc7 (by datasource CNX32_34)

	datasource CNX32_34) + Switch CNX32SW1 configuration changed (by datasource CNX32_34) + Switch CNX32SW3 configuration changed (by datasource CNX32_34) + Switch CNX34SW1 configuration changed (by datasource CNX32_34) + Host SSUNDBP06 configuration changed (by datasource CNX32_34)
11/30/06 6:31 PM	+ Link added between Host SHPP33 port 50:06...82 and Switch TP_CNx08_SW2_ED140M port fc41 (by datasource CNX08) + Link added between Generic Device 50:06:0B:00:00:86:0E:3D port 50:06...3C and Switch TP5_CNx08_SW1_ED140M port fc115 (by datasource CNX08) + Generic Device 50:06:0B:00:00:86:0E:3D is up (by datasource CNX08) + Switch TP5_CNx08_SW1_ED140M configuration changed (by datasource CNX08) ✓ + Switch TP_CNx08_SW2_ED140M configuration changed (by datasource CNX08) + Host SHPP33 configuration changed (by datasource CNX08)
11/30/06 6:31 PM	+ Link added between Host SHPP33 port 50:06...D6 and Switch TP5_CNx06_SW1_ED140M port fc41 (by datasource CNX06_CNx31) + Host SHPP33 is up (by datasource CNX06_CNx31) ✓ + Switch TP5_CNx06_SW1_ED140M configuration changed (by datasource CNX06_CNx31)
11/30/06 6:16 PM	+ Link removed between Host SHPP33 port 50:06...82 and Switch TP_CNx08_SW2_ED140M port fc41 (by datasource CNX08) + Link removed between Generic Device 50:06:0B:00:00:86:0E:3D port 50:06...3C and Switch TP5_CNx08_SW1_ED140M port fc115 (by datasource CNX08) + Host SHPP33 is down (by datasource CNX08) + Generic Device 50:06:0B:00:00:86:0E:3D is down (by datasource CNX08) ✓ + Switch TP5_CNx08_SW1_ED140M configuration changed (by datasource CNX08) + Switch TP_CNx08_SW2_ED140M configuration changed (by datasource CNX08)
11/30/06 6:16 PM	+ Link removed between Host SHPP33 port 50:06...D6 and Switch TP5_CNx06_SW1_ED140M port fc41 (by datasource CNX06_CNx31) + Switch TP5_CNx06_SW1_ED140M configuration changed (by datasource CNX06_CNx31) ✓ + Host SHPP33 configuration changed (by datasource CNX06_CNx31)
11/30/06 6:10 PM	+ 5 Violations created between Host SHPU57 and Storage Sym-00937 (by datasource CNX09CT) + 5 Violations created between Host SHPU58 and Storage Sym-00937 (by datasource CNX09CT) + Link removed between Host SHPU57 port 50:06...A4 and Switch CT_CNx11_SW3 port fc37 (by datasource CNX09CT) + Link removed between Host SHPU57 port 50:06...9C and Switch CT_CNx09_SW2 port fc37 (by datasource CNX09CT) + Link removed between Host SHPU58 port 50:06...34 and Switch CT_CNx11_SW3 port fc38 (by datasource CNX09CT) + Link removed between Host SHPU58 port 50:06...54 and Switch CT_CNx09_SW2 port fc38 (by datasource CNX09CT) + Link removed between Generic Device 50:06:0B:00:00:85:F8:23 port 50:06...22 and Switch CNX11SW2 port fc37 (by datasource CNX09CT) + Link removed between Generic Device 50:06:0B:00:00:85:F8:3F port 50:06...3E and Switch CNX11SW2 port fc38 (by datasource CNX09CT) + Host SHPU57 is down (by datasource CNX09CT) ✓ + Host SHPU58 is down (by datasource CNX09CT) + Generic Device 50:06:0B:00:00:85:F8:23 is down (by datasource CNX09CT) + Generic Device 50:06:0B:00:00:85:F8:3F is down (by datasource CNX09CT) + Switch CNX11SW2 configuration changed (by datasource CNX09CT) + Switch CT_CNx09_SW2 configuration changed (by datasource CNX09CT) + Switch CT_CNx11_SW3 configuration changed (by datasource CNX09CT)
11/30/06 6:01 PM	+ Link added between Host SHPP33 port 50:06...82 and Switch TP_CNx08_SW2_ED140M port fc41 (by datasource CNX08) + Link added between Generic Device 50:06:0B:00:00:86:0E:3D port 50:06...3C and Switch TP5_CNx08_SW1_ED140M port fc115 (by datasource CNX08) ✓

	+ Generic Device 50:06:0B:00:00:86:0E:3D is up (by datasource CNX08)
	+ Switch TP5_CNX08_SW1_ED140M configuration changed (by datasource CNX08)
	+ Switch TP_CNX08_SW2_ED140M configuration changed (by datasource CNX08)
	+ Host SHPP33 configuration changed (by datasource CNX08)
11/30/06 6:01 PM	+ Link added between Host SHPP33 port 50:06...D6 and Switch TP5_CNX06_SW1_ED140M port fc41 (by datasource CNX06_CNX31)
	+ Host SHPP33 is up (by datasource CNX06_CNX31) ✓
	+ Switch TP5_CNX06_SW1_ED140M configuration changed (by datasource CNX06_CNX31)
11/30/06 5:31 PM	+ Link removed between Host SHPP33 port 50:06...82 and Switch TP_CNX08_SW2_ED140M port fc41 (by datasource CNX08)
	+ Link removed between Generic Device 50:06:0B:00:00:86:0E:3D port 50:06...3C and Switch TP5_CNX08_SW1_ED140M port fc115 (by datasource CNX08)
	+ Host SHPP33 is down (by datasource CNX08) ✓
	+ Generic Device 50:06:0B:00:00:86:0E:3D is down (by datasource CNX08)
	+ Switch TP5_CNX08_SW1_ED140M configuration changed (by datasource CNX08)
	+ Switch TP_CNX08_SW2_ED140M configuration changed (by datasource CNX08)
11/30/06 5:31 PM	+ Link removed between Host SHPP33 port 50:06...D6 and Switch TP5_CNX06_SW1_ED140M port fc41 (by datasource CNX06_CNX31)
	+ Switch TP5_CNX06_SW1_ED140M configuration changed (by datasource CNX06_CNX31) ✓
	+ Host SHPP33 configuration changed (by datasource CNX06_CNX31)
11/30/06 4:03 PM	+ Fabric/VSAN CNX34SW1 on principal CNX34SW1 configuration changed (by datasource CNX10_12)
11/30/06 4:01 PM	+ Fabric/VSAN CNX10SW1 on principal TP5_CNX10SW1 configuration changed (by datasource CNX10_12)
11/30/06 3:46 PM	+ 2 Violations resolved between Host APACSGWINU1071 and Storage USP@163.37.197.71 (by datasource CNX05) ✓
	+ Link added between Host APACSGWINU1071 port 10:00...C7 and Switch CT_CNX05_ED140_SW1 port fc125 (by datasource CNX05)
	+ Host APACSGWINU1071 is up (by datasource CNX05)
	+ Switch CT_CNX05_ED140_SW1 configuration changed (by datasource CNX05)
11/30/06 3:31 PM	+ 2 Violations created between Host APACSGWINU1071 and Storage USP@163.37.197.71 (by datasource CNX05)
	+ Link removed between Host APACSGWINU1071 port 10:00...C7 and Switch CT_CNX05_ED140_SW1 port fc125 (by datasource CNX05) ✓
	+ Host APACSGWINU1071 is down (by datasource CNX05)
	+ Switch CT_CNX05_ED140_SW1 configuration changed (by datasource CNX05)